

 **the ExPro**
EXPERIENCE

04/13/2022

NEEDLE IN THE HAYSTACK

Our recent troubleshooting journey to find a shorted wire at a shopping center!




All photos © Exterior Products 2022



Lamps throughout the parking lot were flickering on and off when we arrived.




In troubleshooting, we went to various poles and pull boxes and tested connections.



The process is not random! We always reference our plans and keep track of what we check.



The problem wire is found!



Plotting the new connection.



A trench is dug and the new wire is installed!